





## State Water Resources Control Board

February 12, 2016

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8019 5982

Mr. Collins Kalu
Los Angeles County Metropolitan
Transportation Authority
One Gateway Plaza
Los Angeles, California 9002
kaluc@metro.net

SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS

LOCATED AT METRO DIVISION 3, 630 WEST AVENUE 28, LOS ANGELES

Dear Mr. Kalu:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on February 3, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

| No. | Violation   | Tank                      | Start Date          | Stop Date | Regulation                                |
|-----|---|---------------------------|---------------------|-----------|---|
| 1   | Failure to Maintain Operating Permit On-Site — The facility permit to operate was not on-site at the time of inspection.  | All                       | February 3,<br>2016 | Ongoing   | 23 CCR<br>2712(i)                         |
| 2   | Failure to Tag Monitoring Equipment – The line leak detector was not tagged at the time of inspection.  | T19                       | February 3,<br>2016 | Ongoing   | 23 CCR<br>2641(j)                         |
| 3   | Failure to Monitor Product Piping – Sensors in the sumps are unable to detect a leak at the earliest opportunity because a collar inside the sump prevents the sensors from detecting leaks in all areas of the sump. | T17,<br>T19<br>and<br>T27 | February 3,<br>2016 | Ongoing   | 23 CCR<br>2630(d)                         |
| 4   | Failure to Install Line Leak Detectors – Pneumatic pumps have pressurized underground piping without line leak detectors.   | T17                       | February 3,<br>2016 | Ongoing   | H&SC<br>25291(f);<br>23 CCR<br>2636(f)(2) |

| 5 | Failure to Meet Spill Containment Requirements – Spill container had sludge inside of it; this prevents its ability to hold five gallons.                                      | T27 | February 3,<br>2016 | Ongoing | 23 CCR<br>2635(b)(1) |
|---|--|-----|---------------------|---------|----------------------|
| 6 | Failure to Maintain Primary and/or<br>Secondary Containment – The<br>unleaded piping sump has liquid at<br>bottom and a strong smell of ethanol<br>indicating a possible leak. | T19 | February 3,<br>2016 | Ongoing | H&SC<br>25291(a)     |
| 7 | Failure to Maintain Secondary Containment – The failed components listed on the December 4, 2013 secondary containment test have not been repaired or retested.                | All | December 4,<br>2013 | Ongoing | H&SC<br>25291(a)(2)  |

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Los Angeles City Fire Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

## State Water Board

Ms. Rebecca Green
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16<sup>th</sup> Floor
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

## **Local CUPA**

Mr. Reynaldo Husband
Fire Inspector
Los Angeles City Fire Department
200 Main Street, Suite 1700
Los Angeles, California 90012
reynaldo.husband@lacity.org

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

**UST Enforcement Unit** 

Office of Enforcement

cc: See next page.

cc: (via email only)

Captain Daniel Dragotto
Los Angeles City Fire Department
daniel.dragotto@lacity.org

Mr. Reynaldo Husband Fire Inspector Los Angeles City Fire Department reynaldo.husband@lacity.org

Mr. James Jimenez
Environmental Compliance & Services Manager
Los Angeles County Metropolitan
Transportation Authority
jimenezja@metro.net

Mr. Roger Uhden
Sr. Environmental Specialist & Quality Assurance
Los Angeles County Metropolitan
Transportation Authority
uhdenr@metro.net